

HADER-SEITZ

Change Order Title:**X7741****Detailed Description:**

TORQUE WRENCH HOLE DEPTH CHANGED FROM .375 TO .310.

ECO Properties

Change Order Number: ECN-11158	State: Create
Due Date: 4/17/2014	Submitted by:
Date Submitted:	

Properties

sample 12334	
---------------------	--

Attached Files

File Name	Version	Revision
X-7741.ipt	14	D
X-7741.idw	11	D